



School Facilities and Organization
INFORMATION AND CONDITION OF SCHOOLS
Detailed Condition Assessment by Building
Reporting Year 2024-2025

WOODLAND

92.99%

WOODLAND HIGH SCHOOL (NEW) - AUXILIARY GYM

Building Details

PROFILE TYPE	Gymnasium
NUMBER OF FLOORS	1
BOARD ACCEPTANCE DATE	6/26/2017
CHARACTERISTICS	Occupied
ANNUAL REVIEW COMPLETED BY	District

This building is required to comply with the Asset Preservation Program

REPORTING YEAR	APP YEAR	BUILDING CONDITION ASSESSMENT	ANNUAL REVIEW COMPLETED BY	BOARD REPORT PRESENT DATE
2024-2025	7	92.99	District	3/27/2025
2023-2024	6	92.99	Consultant	Not Reported
2022-2023	5	Not Reviewed	Incomplete	Not Reported
2021-2022	4	Not Reviewed	Incomplete	Not Reported
2020-2021	3	Not Reviewed	Incomplete	Not Reported
2019-2020	2	Not Reviewed	Incomplete	Not Reported

The next certified BCA is due: 2029

Building Inventory

AREA YEAR BUILT	DISTRICT ASSIGNED AREA	GROSS BUILDING SQ FT	GROSS INSTRUCTIONAL SQ FT	SCAP RECOGNIZED SQ FT	ORIGINAL OCCUPANCY DATE	ORIGINAL BOARD ACCEPTANCE DATE
2014	Area 1	6,468	6,468	6,468		6/26/2017
Building Totals		6,468	6,468	6,468		

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Foundations	Standard Foundation	A1010		100.00% Excellent
Slabs on Grade	Standard Slabs on Grade	A4010		100.00% Excellent
Water and Gas Mitigation	Building Subdrainage	A6010		90.00% Good
Superstructure	Roof Construction	B1020		90.00% Good



School Facilities and Organization
INFORMATION AND CONDITION OF SCHOOLS
Detailed Condition Assessment by Building
Reporting Year 2024-2025

WOODLAND

92.99%

WOODLAND HIGH SCHOOL (NEW) - AUXILIARY GYM

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Exterior Vertical Enclosures	Exterior Walls	B2010		90.00% Good
	Exterior Windows	B2020		90.00% Good
	<i>Comments:</i>			
	Exterior Doors and Grilles	B2050		90.00% Good
Exterior Horizontal Enclosures	Exterior Louvers and Vents	B2070		90.00% Good
	Roofing	B3010		90.00% Good
	Roof Appurtenances	B3020		90.00% Good
	Horizontal Openings	B3060		90.00% Good
Interior Construction	Overhead Exterior Enclosures	B3080		90.00% Good
	Interior Partitions	C1010		100.00% Excellent
	Interior Doors	C1030		90.00% Good
	Interior Grilles and Gates	C1040		90.00% Good
Interior Finishes	Wall Finishes	C2010		90.00% Good
	Interior Fabrications	C2020		90.00% Good
	Flooring	C2030		100.00% Excellent
	Ceiling Finishes	C2050		100.00% Excellent
Plumbing	Domestic Water Distribution	D2010		100.00% Excellent
	Sanitary Drainage	D2020		100.00% Excellent
	Building Support Plumbing Systems	D2030		100.00% Excellent
HVAC	Facility Fuel Systems	D3010		90.00% Good
	Heating Systems	D3020		90.00% Good
	Facility HVAC Distribution Systems	D3050		90.00% Good



School Facilities and Organization
INFORMATION AND CONDITION OF SCHOOLS
Detailed Condition Assessment by Building
Reporting Year 2024-2025

WOODLAND

92.99%

WOODLAND HIGH SCHOOL (NEW) - AUXILIARY GYM

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
HVAC	Ventilation	D3060		90.00% Good
Fire Protection	Fire Suppression	D4010		90.00% Good
	Fire Protection Specialties	D4030		90.00% Good
Electrical	Facility Power Generation	D5010		90.00% Good
	Electrical Services and Distribution	D5020		90.00% Good
	General Purpose Electrical Power	D5030		90.00% Good
	Lighting	D5040		90.00% Good
	Comments:	LED Driver issues appear to have been resolved.		
Communications	Data Communications	D6010		90.00% Good
	Voice Communications	D6020		90.00% Good
	Audio-Video Communications	D6030		90.00% Good
	Distributed Communications and Monitoring	D6060		90.00% Good
Electronic Safety and Security	Access Control and Intrusion Detection	D7010		90.00% Good
	Electronic Surveillance	D7030		90.00% Good
	Detection and Alarm	D7050		90.00% Good
Integrated Automation	Integrated Automation Facility Controls	D8010		90.00% Good
Equipment	Commercial Equipment	E1030		90.00% Good
	Institutional Equipment	E1040		90.00% Good
	Entertainment and Recreational Equipment	E1070		62.00% Fair
	Deficiencies:	Other		



WOODLAND HIGH SCHOOL (NEW) - AUXILIARY GYM

Building Components

SUB-ASSEMBLY	COMPONENT	COMPONENT CODE	MAINTENANCE PRIORITY	CONDITION RATING
Equipment	Causes:	Other		
	Comments:	Worn conditions, but functional		
Furnishings	Fixed Furnishings	E2010		90.00% Good
	Movable Furnishings	E2050		90.00% Good