

A wide-angle, slightly elevated photograph of a modern school campus. The main building is a long, two-story structure with a mix of light-colored panels and dark window frames. In the foreground, there's a paved walkway with some greenery and a few people walking. The sky is bright blue with scattered white clouds. The entire image has a light, semi-transparent overlay.

Woodland Public Schools

Facilities and Safety Report
November 2016



FACILITIES REPORT

Combustible Gas detectors – I have been working with Cascade natural Gas's subcontractor getting a proposal to install a combustible gas detector system for WMS. Most of the schools use natural gas for heating water and distributing the water to HVAC equipment through out the schools. WMS is a unique in that all of the classrooms use natural gas to heat the rooms through an indirect heat exchanger. This requires natural gas to be plumbed the length of the yellow and green halls directly above the rooms. This installation requires multiple mechanical joints and flexible connections in the attic space directly above the rooms. This system will detect a leak and alarm to the WMS office forcing an evacuation of the school. The system will also be capable of isolating the gas supply to the school should a leak develop.








Emergency Action plan – I am waiting for the reunification Memorandum of Understanding (MOU's) before issuing the plan to the Superintendent. Once these documents are receive a final edit will be completed and the plan will be submitted.

Card Key Access System – All final proposals have been received for the card key access systems for WPS, WIS, WMS. A final review of the proposals is in progress. A recommendation letter will be submitted to the board for financial approval. System installation is approximately 6-8 weeks and if all goes smoothly, I would expect the system to go live at spring break.

FACILITY CHARTS – POWER COST AND WORK ORDER STATUS



FACILITY CHARTS – WATER USAGE, WHS, WIS, WMS, WPS



Water bills are issued every two months. Next update on these graphs will be in January (Decembers report)

SAFETY

Accidents for the month

There were a total of 11 injuries in the month of November 3 students and 8 staff members.

Staff Accidents/Incidents (8)

- WPS – Student kicked and hit employee
- WPS – Student kicked IA multiple times
- WPS – Student threw chair at teacher
- WPS – Student hit employee in the arm
- WPS – Student bit IA
- WPS – Student struck IA in face and pulled her hair
- WIS – Employee slipped on wet floor
- WPS – Employee slipped on wet floor

Student Accidents/injuries

- WPS – Student received head injury from play equipment (student was pushed)
- WPS – Student slipped on wet floor
- WHS – Student dropped bench on foot

SAFETY CHARTS

